

FIG. 5




FIG. 6






FIG. 7





FOR RAPID TRAVERSE FOR PRESSURIZATION INTE-GRATION INTE-GRATION 114 124 ANGULAR SPEED DIS-TURBANCE ANGULAR SPEED 113 123 INERTIA MOMENT INERTIA MOMENT DIS-TURBANCE FIG. 9 117 127 TORQUE TORQUE SPEED LOOP SPEED LOOP 112 122 116 126 POSITION LOOP POSITION LOOP F 121 115 125 TIME 101 NOITIZOA




FIG. 11B



